

In The United States Patent And Trademark Office

Applicant: Vesa Ahvenniemi et al. Date: January 27, 2012
Date Filed: May 23, 2006 Docket No.: METSO-57
App. No.: 10/595978 Art Unit: 2482
Patent No.: 7,932,922 Issue Date: April 26, 2011
For: Method and Arrangement in Tail Examiner: Anand Shashikant
Threading of a Web Forming
Machine Rao

Filed by Electronic Filing System

Notice of Printing Error

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450


Dear Sir:

A review of the above identified Letters Patent has indicated the existence of the following printing error:

Column 7, line 31, "0.02 lux at f₁" should be - - 0.02 lux at f₁ - - as indicated in the original filing of the patent application, page 16, line 4 of the Clean Copy of Substitute Specification under 37 C.F.R. 1.125(c).

It is requested that this Notice of Printing Error be placed in the file wrapper of the above-referenced Letters Patent in order to complete the record.

Respectfully Submitted,



Patrick J. G. Stiennon, Reg. No. 34934
Attorney for Applicant
Stiennon & Stiennon
P.O. Box 5649
Madison, Wisconsin 53705-5649
(608) 250-4870